

To: David S. Peer[DPeer@mlgasinc.com]
From: Restaino, Mark
Sent: Tue 6/27/2017 1:36:03 PM
Subject: RE: Underground Storage Tank Inspections

This should not be a problem.

-----Original Message-----

From: David S. Peer [mailto:DPeer@mlgasinc.com]
Sent: Monday, June 26, 2017 9:34 AM
To: Restaino, Mark <restaino.mark@epa.gov>
Subject: RE: Underground Storage Tank Inspections

Mark,

I don't quite have everything together for you yet. I got caught up in budget meetings this month. I would like to request another 30 days for completion, but hope to finish it up during the coming week. Thanks you for your consideration!

David Peer
NGO Division Manager
320-655-4412
Cell 320-279-2982

From: Restaino, Mark [restaino.mark@epa.gov]
Sent: Friday, May 26, 2017 2:05 PM
To: David S. Peer
Cc: Ryan.rupp@millelacsband.com; Andrew.Boyd@millelacsband.com
Subject: Underground Storage Tank Inspections

Dave,

Thanks for getting meeting with me regarding the inspections of your underground storage tank facilities. I just wanted to quickly summarize our discussion and make sure it was understood what was needed to complete the inspections.

Here is a list of the items that we need for each facility. If there is an error or you need clarification please feel free to give me a call.

East Lake
Required:

- 1) Conduct an inspection of the of the automatic shutoff overfill device for each tank. Ensure that is operating properly and is set at the correct height.
- 2) Make sure all sheer valves are properly anchored.
- 3) Provide copies of your release detection records for the tank and pipe from September 2016 to May 2017.
- 4) Provide a copy of the latest functionality test of the automatic line leak detectors.

Additional suggestions:

- 1) Adjust the levels of the overfill alarm on your ATG to match the automatic shutoff device.

2) While you have the contractor on site conduct a periodic test of the spill buckets. (This would save money and meet the 3 year periodic testing requirements for the new regulations)

Cross Roads C-Store

Required:

- 1) Conduct an inspection of the of the automatic shutoff overfill device for each tank. Ensure that is operating properly and is set at the correct height.
- 2) Repair/Replace the damaged spill bucket
- 3) Provide copies of your release detection records for the tank and pipe from September 2016 to May 2017.
- 4) Provide a copy of the latest functionality test of the automatic line leak detectors.

Additional suggestions:

- 1) Adjust the levels of the overfill alarm on your ATG to match the automatic shutoff device.
- 2) While you have the contractor on site conduct a periodic test of the spill buckets. (This would save money and meet the 3 year periodic testing requirements for the new regulations)

MLB C-Store

Required:

- 1) Make sure all sheer valves are properly anchored.
- 2) Provide copies of your release detection records for the tank and pipe from November 2016 to May 2017.
- 3) Provide a copy of the latest functionality test of the automatic line leak detectors.

Additional suggestions:

- 1) Adjust the levels of the overfill alarm on your ATG to match the automatic shutoff device.
- 2) While you have the contractor on site conduct the periodic test of the spill buckets and the overfill device. (This would save money and meet the 3 year periodic testing requirements for the new regulations)

Former Meleen's Sport Center

Required:

- 1) Provide copies of your release detection records for the tank and pipe.
- 2) Fill out notification form.

Additional suggestions:

- 1) While you have the contractor on close by conduct the periodic test of the spill buckets and the overfill device. (This would save money and meet the 3 year periodic testing requirements for the new regulations)

Mark Restaino

Underground Storage Tanks Section
Land and Chemicals Division
U.S. EPA Region 5
77 W. Jackson Blvd. (LR-17J)
Chicago, IL 60604
Phone: (312) 886-0394
Fax: (312) 582-5872